



## **Installation on a PPG frame.**

1. This is the best method of installation on a PPG unit with the vest outside the swing arm, Velcro tabs can be extended if needed on some frames.
2. This installation is OK but not as good as outside the swing arm, it will still allow the inflation to occur outwards, note the throttle cable is also inside the vest.
3. WRONG installation, the vest should never be installed inside the swing arm of a PPG unit as it will not allow inflation and may even result in damage to the vest if inflated.
4. You need to imagine what the unit will look like when inflated as in this photo so you can judge if there is anything that would stop expansion of the flotation chamber.